



PT40 Plasma



Back Striking Technology



PLASMA



Current	10-40 Amps
Duty Cycle @ 40°C	60% @ 40 Amps
Air Pressure	65-75 psi / 4.4-5.0 Bar
Air Flow	150lpm / 320 scfh
Pilot	Electrode to Tip
Ignition	Without HF

IN THE BOX

- PT40 4Mt Plasma Torch
- Torch Spare Parts Kit

TORCH PACKAGE

PART NO: 94.PT40.4

NUMBER	PART NUMBER	DESCRIPTION
1	96.PR0110	Electrode PR0110 back striking PT25/PT40 (PKT 5)
2	96.60028	Swirl Ring Tecmo PT25/PT40/PT60 Trafimet S45/S54 (PKT 2)
3	96.PD0116-08	Tip Contact B/Strike 0.8mm 30A Tecmo PT25/PT40/PT60 Trafimet S45 (PKT 5)
4	96.PD0116-09	Tip Contact B/Strike 0.9mm 40A Tecmo PT40/PT60 Trafimet S45 (PKT 5)
5	96.60389	Retaining Cap 6 holes Tecmo PT40/PT60, Trafimet S45 (PKT 1)
6	96.60432	Double Pointed Spacer Tecmo PT40/PT60

OPTIONAL ACCESSORIES



TJ1536 Plasma Roller Guide - PT40/PT60



96.TJ1202H Plasma Cutting Circle Guide - PT-60



96.51866 Circle Cutting Attachment
Tecmo PT25/PT40/PT60 Trafimet S45